

1  
R 3687405-407

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**      \$15.00

**TYPE BUILDINGS**

<b>PERMIT NO.</b>					
<b>G-4688</b>	<b>LOCATION</b>	<b>861 - 55th Street A-1 (16)</b>			
<b>DATE</b>	<b>PURPOSE</b>	<b>Const. &amp; enlarge kitchen to rear of</b>			
<b>Sep. 18-69</b>	<b>OWNER</b>	<b>S.R. McWilliam      ?dwlg.</b>			
<b>ZONE</b>	<b>ARCH'T</b>				
	<b>CONT'R</b>	<b>Dawson Const., 4903 Auburn Blvd.</b>			
<b>VAL. \$1,400.</b>		<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
					<b>100 sq.ft.</b>
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>	<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>	
<b>FORM</b>	<i>9-23-69</i>	<i>Bulles</i>			
<b>JOIST</b>	<i>9-24-69</i>	<i>Bulles</i>			
<b>FRAME</b>	<i>10-6-69</i>	<i>Burkhardt</i>			
<b>SHEET ROCK</b>					
<b>FINAL</b>	<i>10-9-69</i>	<i>Burkhardt</i>			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
10-3-69	Exterior Solt incorrect <i>Robert</i>
10-3-69	Windows not flashed in <i>Robert</i> some in crawl hole for <i>Robert</i>
COMPLETE AND OK	INSPECTOR