

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-18832</i>	LOCATION <i>3610 - W. Lincoln Way</i>
DATE <i>5/7/47</i>	PURPOSE <i>Build shower Rm. to rear dwlg.</i>
ZONE	OWNER <i>W. A. Janeych</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>375⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
8/10/33	2 nd fl. N.S.P. Expense for Addition of 2 Bed Rooms on rear of 2 nd Story of Dula. ^{OK} A.W. Campbell
8/16/33	3 rd fl. N.S.P. INT. HATH. ^{OK.} A.W. Campbell
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>