

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD
TYPE BUILDINGS

PERMIT NO. <i>Mch.</i>	LOCATION <i>2000 E. St.</i>
DATE <i>7/24/31</i>	PURPOSE <i>Alter. Rep. Elevator</i>
ZONE <i>Mud. Jan.</i>	PHONES
CONT-R <i>Owner</i>	OWNER <i>on Taber</i>
VAL <i>Wood Cl. 20</i>	ARCH'T
STORIES 	ROOMS
APTS. 	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
8/1/31	Repairs to front steps OK
	All Completed
8/1/31	COMPLETE AND O.K. <i>Allen J. Campbell</i> INSPECTOR

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100