

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-13848</i>	LOCATION <i>2504 - J M</i>			
DATE <i>8/11/45</i>	PURPOSE <i>Replace shaft due to fire</i>			
ZONE	OWNER <i>C. Hahn</i>			
	ARCH'T.			
	CONTR. <i>W^m La Rue</i>			
VAL. <i>1500⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK—REMARKS
	OK
	COMPLETE AND O. K. INSPECTOR