

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT No. <i>A-2793-</i>	LOCATION <i>2316 - 28<sup>th</sup> St.</i>			
DATE <i>5/7/34</i>	PURPOSE <i>Make repairs to dwelling in</i>	PHONES		
ZONE	OWNER <i>Loss. W. M. Wagoner</i>			
	ARCH'T			
	CONT'R <i>Owner</i>			
VAL. <i>500<sup>00</sup></i>	STORIES	ROOMS	APTS.	SIZE
Light Shafts		Elevator Shafts		
Vent Shafts		Boiler Rooms		
Owner's Inspector		Sprinkler System		
Lath		Gas Vents		
Fire Escapes		Chimneys		
Stand Pipes		Skylights		

DATE	CONDITION OF WORK-REMARKS
5/21/35	1 <sup>ST</sup> /NSP. Concret Floor Approach & Retaining Walls.
	For installing Parents Garage under Driv. A.W. Campbell
5/21/35	2 <sup>ND</sup> /NSP. Frame for Partitions <sup>OK</sup> A.W. Campbell
5/27/35	3 <sup>RD</sup> /NSP INT. METAL LATH WALLS & CEILING <sup>OK</sup> A.W. Campbell
6/19/35	4 <sup>TH</sup> /NSP. Above work completed including new wood stairway to basement. <sup>OK</sup> A.W. Campbell
6/19/35	COMPLETE AND O.K. <i>A.W. Campbell</i> INSPECTOR