

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. 15-3701	LOCATION 583 - 50 <sup>th</sup> Street			
DATE 8/28/39	PURPOSE New dwlg. - gar			
ZONE 2 Fam	OWNER Edw. J. Byers			
	ARCH'T. CONT'R. John Fernandez			
VAL. \$5000.00	STORIES 1	ROOMS 5	APTS.	SIZE
LIGHT SHAFTS	ELEVATOR SHAFTS	Area		
VENT SHAFTS	BOILER ROOMS	1300 <sup>+</sup>		
OWNER'S INSPECTOR	SPRINKLER SYSTEM	@ 35 <sup>+</sup>		
LATH	GAS VENTS			
FIRE ESCAPES	CHIMNEYS			
STAND PIPES	SKYLIGHTS			

DATE	CONDITION OF WORK—REMARKS
8/29 39	1st Insp Form of Punter
9-22 39	2 " Form of Punter
	<div style="display: flex; justify-content: space-between;"> <span>COMPLETE AND O. K.</span> <span>INSPECTOR</span> </div>