


BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. 5823 DATE 1/21/34 ZONE	LOCATION 931 S. 11th St. 1210-9	
	PURPOSE Brk. & Auto Rep Shop	PHONES
	OWNER Hanley of Peyton 1216 S.	
	ARCH'T Mr. Peterson	
	CONT'R Mr. Peterson 4530 Parkside Ave	

VAL.	STORIES	ROOMS	APTS.	SIZE
5 ft.				

Steel Tested by		Elevator Shafts	
Cement Tested by		Boiler Rooms	
Owner's Inspector Rfcd. Conc.		Sprinkler System	
		Floor Tests	
Fire Escapes			
Stand Pipes			

DATE	CONDITION OF WORK—REMARKS
2/7/30	1 ST /NSP. Frame In Brick Walls for Public Looz.
	Also 2 Curbs $4 \times 4 \times 1$. Redf. Concrete OK A.W. Campbell
3/3/30	2 ND /NSP. Frame in place. OK A.W. Campbell
3/13/30	3 RD /NSP. - NO LETTING OF POSTING - INT. WHITEWASHED A.W. Campbell
3/17/30	4 TH /NSP. Brick Arch Repair Shop Completed. OK A.W. Campbell
3/17/30	ISSUED CERTIFICATE OF OCCUPANCY # 5873
	Street Cleared up O.K.
3/17/30	COMPLETED AND O.K. <i>Alden W. Campbell</i> INSPECTOR