

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <b>6471</b>	LOCATION <b>1223-33<sup>rd</sup> St.</b>		
DATE <b>June 24 1930</b>	PURPOSE <b>Re-Roof Dwg. with Composition Shingles</b>	ROOMS	APTS.
ZONE <b>Multiple Family</b>	OWNER <b>E. S. TULEY,</b>	PHONE	
	ARCH'T		
	CONT'R <b>STAR ROOF CORP. 1715-5<sup>th</sup> St.</b>		
	VAL. <b>132<sup>00</sup></b>	STORIES <b>1</b>	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
Ex Wall	Jolts						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="324 830 475 875">COMPLETED AND O.K.</p> <p data-bbox="1108 857 1246 875">INSPECTOR</p>