

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. B-33166	LOCATION 222 1/2 J Street			
DATE 5-27-53	PURPOSE Repair underpinning for storage rm.			
ZONE	OWNER Ronald Davis			
	ARCH'T.			
	CON'T'R. D. W. Fuller			
VAL. \$218.00	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK--REMARKS
4/21/37	Made inspection of repairs being made to
	front steps and settled.
	O.K. A.W. Campbell
4/21/37	<p>COMPLETED AND O.K. <i>Allen W Campbell</i> INSPECTOR</p>