

## BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>9074</i>	LOCATION <i>618-10<sup>th</sup> St.</i>			
DATE <i>1/20/32</i>	PURPOSE <i>Gen Res Dy.</i>	PHONES		
ZONE <i>Gen Com</i>	OWNER <i>J C Moulfort</i>			
	ARCH'T			
	CONT-R <i>Owner</i>			
VAL. <i>350 —</i>	STORIES	ROOMS	APTS.	SIZE
Light Shafts			Elevator Shafts	
Vent Shafts			Boiler Rooms	
Owner's Inspector			Sprinkler System	
Lath			Gas Vents	
Fire Escapes			Chimneys	
Stand Pipes			S Skylights	

DATE	CONDITION OF WORK--REMARKS
2/9/37	<p>Made Frame Inspection for Dwg damaged by storm            Notified Contractor to cut off bottoms of 6x6 frame posts            parts below deck level &amp; raise up 2" above grade.</p> <p style="text-align: right;">A.W. Campbell</p>
2/27/37	<p>Repairs to Dwg Completed OK</p> <p style="text-align: right;">A.W. Campbell</p>
2/27/37	<p>COMPLETE AND O. K.</p> <p style="text-align: center;">A.W. Campbell</p> <p style="text-align: right;">INSPECTOR</p>