

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. 4002	LOCATION 1117-7th
DATE	PURPOSE Gen Remodel
ZONE SAC	OWNER Mrs. F S Smith
ARCH'T.	PHONES
CONT'R J Rude, 2727-16- Cap 2756	

VAL. 1500	STORIES	ROOMS	APTS.	SIZE
------------------	---------	-------	-------	------

Steel Tested by	<i>OMA</i>	Elevator Shafts
Cement Tested by		Boiler Rooms
Owner's Inspector Rfd. Conc.		Sprinkler System
Fire Escapes		Floor Tests
Stand-pipes		



