

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-5846</i>	LOCATION <i>961-55<sup>th</sup> St.</i>
DATE <i>6/25/40</i>	PURPOSE <i>erect new dwlg.</i>
ZONE <i>-</i>	OWNER <i>Q. Haasen</i>
	ARCH'T. <i>C. J. Glisan</i>
	CONTR. <i>C. J. Glisan</i>

VAL. <i>3500<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>area</i> <i>900<sup>00</sup></i> <i>@ 350</i>
VENT SHAFTS	BOILER ROOMS	
OWNER'S INSPECTOR	SPRINKLER SYSTEM	
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

Approved for the City of New York by the Board of Building and Fire Underwriters, Inc.

DATE	CONDITION OF WORK—REMARKS
6/26/40	1 <sup>st</sup> / NSP. Form in place <sup>OK</sup> Neil Campbell
7/18-40	2 " Frame OK Dexter
	T-7-7
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="302 1011 453 1058">COMPLETE AND O. K.</span> <span data-bbox="1293 1034 1461 1058">INSPECTOR</span> </div>