

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <i>739 V</i>	LOCATION <i>(ADDITIONAL PERMIT) 2917 ST.</i>
DATE <i>11/18/30</i>	PURPOSE <i>Rem. Repair Flr. Workshed.</i>
ZONE <i>Multif</i>	OWNER <i>M. Blubich</i>
	ARCH'T
	CONT'R <i>Owner</i>
	VAL. <i>500-</i>
	STORIES
	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
EX WALL	Joists						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	CONDITION OF WORK—REMARKS
11/26/31	Notified Owner & take out this additional Permit for Work. Shed need for additional repairs to Bldg not covered by Original Permit. W.A. Campbell
	COMPLETED AND O.K. INSPECTOR