

## BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <b>B-5896</b>	LOCATION <b>5216 - U St</b>				
DATE <b>7/1/40</b>	PURPOSE <b>Erect new dwg</b>				
ZONE <b>-</b>	OWNER <b>W. W. Hunt Jr - J</b>				
	ARCH'T. <b>R. H. Strickler</b>				
	CONT'R. <b>R. H. Strickler</b>				
VAL. <b>3500</b>	STORIES <b>1</b>	ROOMS <b>3</b>	APTS.	SIZE	
LIGHT SHAFTS		ELEVATOR SHAFTS	<b>area 950 sq ft @ 3.50</b>		
VENT SHAFTS		BOILER ROOMS			
OWNER'S INSPECTOR		SPRINKLER SYSTEM			
LATH		GAS VENTS			
FIRE ESCAPES		CHIMNEYS			
STAND PIPES		SKYLIGHTS			

DATE	CONDITION OF WORK--REMARKS	
	1 <sup>st</sup>	Insp Frame of <i>P</i>
7-12-40	2 "	Frame of <i>P</i>
7-25-40	3 "	Lath & Plaster " <i>P</i>

COMPLETE  
AND O. K.

INSPECTOR