

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-3401-</i>	LOCATION <i>5475-5th St.</i>
DATE <i>4/26/40</i>	PURPOSE <i>Repairs to dwg duct to fire</i>
ZONE	OWNER <i>E. C. Cooney</i>
	ARCH'T.
	CONT'R. <i>H. C. Pratt</i>

VAL. <i>580⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

..DATE.	CONDITION OF WORK-REMARKS
	<i>Fire 1st</i>
<i>4/29 30</i>	<i>2nd Trip Found 2 Pipes</i>
	<p>COMPLETE AND O. K.</p> <p>INSPECTOR</p>