

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-25180</i> DATE <i>4-25-49</i> ZONE	LOCATION <i>1019 1/2 J street.</i>
	PURPOSE <i>Repair to Hg.</i>
	OWNER <i>Boyd Leachman</i>
	ARCH'T.
	CONT'R. <i>J Paul Howell</i>

VAL. <i>\$200</i>	STORIES	ROOMS	APTS.	SIZE
-------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
5/25/49	Rear Storage Room O.K. J. E. Puckins
	COMPLETE AND O. K. INSPECTOR