

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD.

TYPE BUILDINGS

PERMIT No. <i>A-894</i>	LOCATION <i>2001 N Street</i>			
DATE <i>Aug 30-33</i>	PURPOSE <i>Alterations & repairs to store</i>			
ZONE <i>Sen Com.</i>	OWNER <i>W. H. Enos</i>			
	ARCH'T <i>" " " day work</i>			
	CONT-R <i>Owner ✓</i>			
VAL. <i>15000</i>	STORIES <i>3</i>	ROOMS	APTS.	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK—REMARKS
8/30/33	Made Preliminary Inspection, with Shultz, for Permit for Alterations to 1 st floor for Grocery Store. New Entrance Door. Install Plate Glass Window on 70" SF side and make repairs & plumbing in rear.
9/13/33	A TH Insp. Above work complete O.K.
9/13/33	COMPLETE AND O. K. <i>Alfred A. Campbell</i> INSPECTOR