

BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. 9987	LOCATION 425-8th Street			
DATE 10-4-37	PURPOSE Repair to Brick Bldg			
ZONE	OWNER Philip Wolf			
	ARCH'T			
	CONT-R EP Schlueter			
VAL. 150.00	STORIES	ROOMS	APTS.	SIZE

Light Shafts	Elevator Shafts
Vent Shafts	Boiler Rooms
Owner's Inspector	Sprinkler System
Lath	Gas Vents
Fire Escapes	Chimneys
Stand Pipes	Skylights

