

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

5 TYPE BUILDINGS

PERMIT NO. B - 38951	LOCATION 4017 53rd Street
DATE 9-22-53	PURPOSE Repair fire damage to ori gar
ZONE	OWNER W. W. Fowler
	ARCH'T.
	CONTR. "

VAL. \$500	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS				
VENT SHAFTS				
OWNER'S INSPECTOR				
LATH				
FIRE ESCAPES				
STAND PIPES				
			ELEVATOR SHAFTS	
			BOILER ROOMS	
			SPRINKLER SYSTEM	
			GAS VENTS	
			CHIMNEYS	
			SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
7-29-53	Frame (Burned Car) M.A. Hummer
	COMPLETE AND O. K. INSPECTOR