

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

**TYPE BUILDINGS**

<b>PERMIT NO.</b> B-38064 <hr/> <b>DATE</b> 5-18-53 <hr/> <b>ZONE</b>	<b>LOCATION</b> 5926 55th Street
	<b>PURPOSE</b> Roof over patio and erect 3' block wall.
	<b>OWNER</b> H. Wentsch
	<b>ARCH'T.</b>
	<b>CONTR.</b> Owner

<b>VAL.</b> \$430.00	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
----------------------	----------------	--------------	--------------	-------------

<b>LIGHT SHAFTS</b>		<b>ELEVATOR SHAFTS</b>	
<b>VENT SHAFTS</b>		<b>BOILER ROOMS</b>	
<b>OWNER'S INSPECTOR</b>		<b>SPRINKLER SYSTEM</b>	
<b>LATH</b>		<b>GAS VENTS</b>	
<b>FIRE ESCAPES</b>		<b>CHIMNEYS</b>	
<b>STAND PIPES</b>		<b>SKYLIGHTS</b>	

Department of Building Inspection, City of New York, 100 City Hall, New York 10007

DATE	CONDITION OF WORK—REMARKS
10-20-53	Frame + Final Don Berry
	COMPLETE AND O. K. INSPECTOR