

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-6952</i>	LOCATION <i>1070 - 45th St.</i>			
DATE <i>11/8/40</i>	PURPOSE <i>Make addn & rearranging</i>			
ZONE	OWNER <i>J. O'Neill</i>			
	ARCH'T. <i>Paul Johnson & Son</i>			
	CONTR. <i>Paul Johnson & Son</i>			
VAL. <i>2800⁰⁰</i>	STORIES <i>2</i>	ROOMS <i>2</i>	APTS. <i>1</i>	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE

CONDITION OF WORK—REMARKS

12-11

20' deep trench on center

COMPLETE
AND O. K.

INSPECTOR