

R213 F 365-306

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$24.00

TYPE BUILDINGS

PERMIT NO.					
H-3856		LOCATION 6050 - 34th Avenue		A-4 (32.02)	
DATE		PURPOSE Const. det. garage on rear of lot			
Oct. 18-71		OWNER Mrs. Velma Davis Same			
ZONE		ARCH'T			
R-1		CONTR United Remodeling Sys. 7133-Power Inn			
VAL. \$1,800.		STORIES 1	ROOMS	APTS.	/Road SIZE 500 sq. ft.
INSP.	DATE	BLDG. TYPE		OCCUPANCY GROUP	PHONE (O) (C) 383 7722
FORM	11-17-71	Photo			
JOIST					
FRAME	12-17-71	Photo & plan photo			
SHEET ROCK					
FINAL	1-25-72	J. M. White			

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|----------|--|
| 11-16-71 | P. from - no mudside hole |
| 12-12-71 | P. 3400 - hole missing - stage mud
no toe drilled R.H. |
| 1-18-72 | P. 3400 - mudstone in place
no ready G. 2000 |
| | |
| | |
| | |
| | |
| | <p>COMPLETE AND OK</p> <p style="text-align: right;">INSPECTOR</p> |