

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>H-2337</i>	LOCATION <i>2947 - 35th Street,</i>			
DATE <i>12/6/34</i>	PURPOSE <i>To hang new elevator sign.</i>			
ZONE <i>Gen Com</i>	OWNER <i>H. L. Woods</i>			
	ARCH'T <i>Elec. Sign Serv Co</i>			
VAL. <i>250⁰⁰</i>	CONT'R <i>Elec. Sign Serv Co</i>			
	STORIES	ROOMS	APTS.	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
12/6/50	<p> Made inspection of inside portion of Electric Panel Face. Found 12 ft above sidewalk & 4 ft from 3rd floor Face of wall. Panel was found to be in good condition. Panel was trapped over fire wall. OK R. W. Campbell </p>
12/15/50	<p> COMPLETE AND O. K. <i>R. W. Campbell</i> INSPECTOR </p>

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-2337</i>	LOCATION <i>2947 - 35th Street -</i>			
DATE <i>12/6/34</i>	PURPOSE <i>To hang 1 - new Elec. Reg'n.</i>			
ZONE <i>Gen. Com.</i>	OWNER <i>H. L. Woods.</i>			
	ARCH'T			
	CONT'R <i>Elec. Reg'n. Serv. Co.</i>			
VAL. <i>25000</i>	STORIES	ROOMS	APTS.	SIZE
Light Shafts		Elevator Shafts		
Vent Shafts		Boiler Rooms		
Owner's Inspector		Sprinkler System		
Lath		Gas Vents		
Fire Escapes		Chimneys		
Stand Pipes		Skylights		

DATE

CONDITION OF WORK—REMARKS

COMPLETE
AND O. K.

INSPECTOR