

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-2609</i>	LOCATION <i>2649-Montgomery Way.</i>			
DATE <i>8/12/49</i>	PURPOSE <i>Repairs due to termites at address</i>			
ZONE	OWNER <i>G. E. Wachorst</i>			
	ARCH'T.			
	CONTR. <i>E. W. Gacklinghouse</i>			
VAL. <i>1500⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
8/10/49	Forms Insp. <i>ASG</i>
9/12/49	Frame " " " "

COMPLETE
AND O. K.

INSPECTOR