

**RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA**

PROPERTY PARCEL NO.		JOB ADDRESS <b>115 Barton Way</b>					INSPECTION AREA	FINAL INSPECTIONS		
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY	DATE
TITLE AND NAME			1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.	ELECTRICAL BY	DATE
GEN. CONTR.									PLUMBING BY	DATE
ELEC. CONTR.									MECHANICAL BY	DATE
PLBG. CONTR.										
MECH. CONTR.										
ARCH. ENGR.										
OWNER									CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER									ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE		
						CENSUS TRCT. NO.				
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED		

**NATURE OF WORK:-**

PERMIT NO. S.P. -		<b>MICROFILM RECORD</b>			
ISSUED BY					
ISSUANCE DATE		PLANS AND APPLICATION	REEL NO.	FRAME NO:-	TO
VALUATION	\$	INSPECTION RECORD	REEL NO.	FRAME NO:-	TO
R.D.F. FEE	\$	JOB FILE	REEL NO.	FRAME NO:-	TO
S.M.I. FEE	\$				
PLAN CK. FEE	\$				
SEWER INCL. FEE	\$				
PERMIT FEE	\$	REMARKS AND/OR VARIANCES			
	\$				
	\$				
TOTAL FEES	\$				

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
8-9-71	Bldg. 2,000.	H-2732 24.00	repair fire damage	Lloyd Coluin	Owner	<i>M. J. McManis</i>	11-12-71


MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
H-2732	R-308 F.655	K422F203	3/27/71		

H-2732  
H-2732  
R-308 F.655  
K422F203  
3/27/71