


**BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD
TYPE BUILDINGS**

PERMIT NO.	LOCATION	
8365	241 Hillborn Oaks 2933 - Way	
DATE	PURPOSE	PHONES
8/4/31	Fr 8x10y6 Pnd 1	
ZONE	OWNER	
2 Fam	Fr 8x10y6 Pnd 1	
	ARCHT	
	Fr 8x10y6 Pnd 1	
	CONT-R	
	Fr 8x10y6 Pnd 1	

VAL.	STORIES	ROOMS	APTS.	SIZE
5000	1	6	1	3-2-2

Light Shafts	Elevator Shafts
Vent Shafts	Boiler Rooms
Owner's Inspector	Sprinkler System
Lath	Gas Vents
Fire Escapes	Chimneys
Stand Pipes	Skylights

DATE	CONDITION OF WORK-REMARKS
8/12-31	1 st Insp Form in place of P.H. Tests
9/2-31	2 " Frame of mast chimney P.H. Tests
11/2-31	3 " Ext Lath of P.H. Tests
9/10-31	3 rd Int " " P.H. Tests
10/30-31	4 " Final Insp. Certificate of
	occupancy issued.
	At Cl Ship
COMPLETE AND O.K.	 INSPECTOR