

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | | | | |
|-------------------------------|------------------------------------|------------------|-------|------|
| PERMIT NO. <i>B-10,697</i> | LOCATION <i>2315-C St.</i> | | | |
| DATE <i>9/14/42</i> | PURPOSE <i>Repairs to dwlg.</i> | | | |
| ZONE | OWNER <i>John Adams</i> | | | |
| | ARCH'T. | | | |
| | CONTR. <i>Owner</i> | | | |
| VAL. <i>2000⁰⁰</i> | STORIES | ROOMS | APTS. | SIZE |
| LIGHT SHAFTS | | ELEVATOR SHAFTS | | |
| VENT SHAFTS | | BOILER ROOMS | | |
| OWNER'S INSPECTOR | | SPRINKLER SYSTEM | | |
| LATH | | GAS VENTS | | |
| FIRE ESCAPES | | CHIMNEYS | | |
| STAND PIPES | | SKYLIGHTS | | |

| DATE | CONDITION OF WORK—REMARKS |
|----------|---|
| 10/21/42 | Owner moved small 1 Room Hdy on rear of lot and added 1 Room for patchwork quarters for self to live in. R W Campbell |
| | |
| | |
| | |
| | COMPLETE AND O. K. INSPECTOR |