

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

**TYPE BUILDINGS**

PERMIT NO. <i>B-11614</i>	LOCATION <i>3320 - J St.</i>
DATE <i>10/1/43</i>	PURPOSE <i>Reshingled</i>
ZONE	OWNER <i>B. S. Phelan</i>
	ARCH'T.
	CONTR. <i>Bush Roofing Co.</i>

VAL. <i>17500</i>	STORIES	ROOMS	APTS.	SIZE
-------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
10/11/43	Re Roofing of Dory with Composite Shingles Completed
10/11/43	COMPLETE AND O. K. <i>William H Campbell</i> INSPECTOR