

MISS 7445

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$22.00

TYPE BUILDINGS

75197 7526 *addition*
plan

PERMIT NO. F-2918	LOCATION 335 34th Street				
DATE 1-25-66	PURPOSE Structural pest repair on dwelling				
ZONE	OWNER Moore and O'Neal 1833 40th St.				
	ARCH'T				
	CONT'R Orchard Supply 1731 17th Street				
VAL. \$5,000.	STORIES	ROOMS	APTS.	SIZE	
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM	7-7-66	Garage (part)	I-1	446-7821	
JOIST					
FRAME	7-1-66	Asph (partial)			
SHEET ROCK					
FINAL	4-13-67	Mc Callaway			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
3-4-66	Pt. Crane - not ready. <i>Hammond</i>
5-13-66	Pt. Crane - not ready. <i>Hammond</i>
7-9-66	OK to lock. Outside. <i>Loren</i>
8-17-66	OK interior & exterior walls. <i>Loren</i>
12-13-66	Recess Basement from O.K. <i>Pride</i>
7-20-67	Unable to get through <i>cellarway</i> <i>penet</i>
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND OK INSPECTOR </div>