

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | |
|----------------------|--------------------------------------|
| PERMIT NO. B-4091 | LOCATION 577-35 th St. |
| DATE 10/23/39 | PURPOSE Erect new dwg. on |
| ZONE | OWNER Roy E. Etter |
| | ARCH'T. |
| | CONTR. F. L. Terra |

| | | | | |
|----------|---------|-------|-------|------|
| VAL. 500 | STORIES | ROOMS | APTS. | SIZE |
|----------|---------|-------|-------|------|

| | |
|-------------------|------------------|
| LIGHT SHAFTS | ELEVATOR SHAFTS |
| VENT SHAFTS | BOILER ROOMS |
| OWNER'S INSPECTOR | SPRINKLER SYSTEM |
| LATH | GAS VENTS |
| FIRE ESCAPES | CHIMNEYS |
| STAND PIPES | SKYLIGHTS |

| DATE | CONDITION OF WORK-REMARKS |
|----------|--|
| 11-14-39 | 2 nd Inop Frame of Printer |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND O. K. INSPECTOR |