

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <i>Michg</i>	LOCATION <i>625-10-</i>		
DATE	PURPOSE <i>Gen Res.</i>	ROOMS	APTS.
ZONE	OWNER <i>La Point</i>	PHONE	
	ARCH'T		
	CONT'R <i>Jon Harting</i>		
	VAL. <i>10 -</i>	STORIES	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF			
Ex Wall	Jolists						Chimneys		Cement Tests
	Beams and Girders						Fire Place		
Int Wall	Studs and Columns						Gas Water Heater		
	Bridging Fire Stops						Heater Closet		
Piers	Fire Escape Stand Pipes						Furnace		Window Courts
	Metal Lath						Boiler Room		
	Stairs						Elevator Shaft		

DATE

CONDITION OF WORK—REMARKS

5/14/27

Contractor repaired S.E. Corner of Hwy
where automobile damaged same.
Repaired with concrete and painted.

5/10/27

COMPLETED
AND O. K.

Repairs completed G. M. [Signature]
Inspector