

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-540</i>	LOCATION <i>1001 - I Street</i>
DATE <i>4/26/40</i>	PURPOSE <i>Erect new store & office bldg</i>
ZONE <i>-</i>	OWNER <i>N. B. & Louis L. Drabcher</i>
	ARCH'T.
	CONTR. <i>Frank Maloney</i>

VAL. <i>125,000</i>	STORIES <i>2</i>	ROOMS	APTS.	SIZE
---------------------	------------------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
5/22/40	1 ST / NSP. Reinf Conc Footing Piers in place ^{OK} AW Campbell
9/18/40	2 ND / NSP. Frame for 3 RD STY ^{OK} AW Campbell
9/27/40	2 ND / NSP. " " 2 ND - 1 ST STY ^{OK} AW Campbell
10/1/40	3 RD / NSP. " " 2 ND - 1 ST STY ^{OK} AW Campbell
10/7/40	3 RD / NSP. Int. LatH Part on 1 ST - 2 ND - 3 RD Floor ^{OK} AW Campbell
10/14/40	3 RD / NSP. INT. LATH Part on 1 ST - 2 ND - 3 RD Floor ^{OK} AW Campbell
10/25/40	3 RD / NSP. Bal. + including Ceiling on 1 ST - 2 ND - 3 RD Floor ^{OK} AW Campbell
12/20/40	4 TH / NSP. Build-up paper, plaster, except interior partitions + some fixtures not been installed as per spec. by Tarrant. New side lairs, and other part + alterations complete
	COMPLETE AND O. K. INSPECTOR