2001 Edison Ave. A-6

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
11/27/67	Bldg.$5,500.00	F-9088$25.00	Repair damage by fire to dwelling	Joan Jaime	Bldg. Council Repair Co. 5821 Rosebud Ln.	Barbato	2/26/68

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
F-9088	R-229F-341				
F-9088	BA96F102- final				

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.	JOB ADDRESS	INSPECTION AREA

LEGAL DESCRIPTION	OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE

TITLE AND NAME	I/C	ADDRESS	ZIP	CITY LIC. NO.	TEL. NO.
GEN. CONTR.					
ELEC. CONTR.					
PLBG. CONTR.					
MECH. CONTR.					
ARCH. ENGR.					
OWNER					
~~CONST. LOAN LENDER~~					

BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE
							CENSUS TRCT. NO.	
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED

NATURE OF WORK:-

PERMIT NO. S.P. -	
ISSUED BY	
ISSUANCE DATE	
VALUATION	$
R.D.F. FEE	$
S.M.I. FEE	$
PLAN CK. FEE	$
SEWER INCL. FEE	$
PERMIT FEE	$
	$
	$
TOTAL FEES	$

MICROFILM RECORD

PLANS AND APPLICATION	REEL NO.	FRAME NO:-	TO
INSPECTION RECORD	REEL NO.	FRAME NO:-	TO
JOB FILE	REEL NO.	FRAME NO:-	TO

REMARKS AND/OR VARIANCES

FINAL INSPECTIONS

BUILDING BY	DATE
ELECTRICAL BY	DATE
PLUMBING BY	DATE
MECHANICAL BY	DATE
CERTIFICATE OF OCCUPANCY	
ISSUED BY	DATE

BI-FI-R