

200 7361 PLO

Q176 766-86

N. side of **BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD** \$165.50

San Juan Rd. W. of Northstead Dr.
Northgate Unit #4

TYPE BUILDINGS

plus 11-17-65
Q191 746 letter

PERMIT NO.		LOCATION		APTS.	
F-1544		925 - San Juan Road		A-6	
DATE		PURPOSE			
Aug 23-65		Const. church (sanctuary & social hall)			
ZONE		OWNER			
Interim		Peace Lutheran Church same			
ARCHT		BLEWETT & HODGSON 405-HOLLY DR. SAN RA.			
CONTR		L. DEVON CONST. 3979-ORANGWOOD DR. F.O.			
VAL. \$63,900.		STORIES	ROOMS	1790-Social site 1.	
				2070 sq. ft.	
INSP.	DATE	BLDG. TYPE	V-no hr.	OCCUPANCY GROUP	PHONE (O) (C)
				B-3	Y07-8215
FORM	<i>9-3-65</i>	<i>Larsen</i>			
JOIST					
FRAME	<i>12-9-65</i>	<i>(near 11/17/65) Larsen</i>			
SHEET ROCK	<i>12-14-65</i>	<i>Hammons 12-27-65</i>			
FINAL	<i>2-14-66</i>	<i>R. Hunt</i>			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
9-2-65	Pt from - No bills on job - Bolts not sent out Larsen
9-15-65	Contr. will call duct work in slab not water proof. OK to cover ducts Larsen
9-16-65	OK duct work in first bldg. Larsen
9-22-65	OK slab Larsen
9-24-65	OK footing for columns Larsen
9-28-65	OK tube slab Larsen
11-8-65	Pt OK - No stamped plans on job Larsen
11-15-65	OK clearance work Larsen
11-16-65	No glass lamp certificate Larsen
11-18-65	Pt No glass lamp certificate Larsen
11-19-65	OK 2" deck roof nail for rear bldg Larsen
11-30-65	OK phosor nail on rear bldg Larsen
12-9-65	OK roof nail on 2" roofing (rear bldg) Larsen
12-10-65	Pt roof nail - not ready Larsen
12-14-65	COMPLETE OK roof nail Larsen
12-29-65	AND OK RJ. 20 - Not ready Larsen
2-11-66	Pt Admiration not ready Crest

INSPECTOR