

BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | |
|--|--|
| PERMIT NO. 9608 | LOCATION 1050-45th St |
| DATE June 23rd 1932 | PURPOSE Make Interior alterations & Repair in Dwp. |
| ZONE 1-Family | OWNER C. E. WRIGHT, |
| | ARCH'T |
| | CONT-R OWNER |

VAL.

500⁰⁰

STORIES

2

ROOMS

APTS.

SIZE

| | | | |
|-------------------|--|------------------|--|
| Light Shafts | | Elevator Shafts | |
| Vent Shafts | | Boiler Rooms | |
| Owner's Inspector | | Sprinkler System | |
| Lath | | Gas Vents | |
| Fire Escapes | | Chimneys | |
| Stand Pipes | | Skylights | |

| DATE | CONDITION OF WORK--REMARKS |
|------|---|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND O. K. INSPECTOR |