

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-10,941</i>	LOCATION <i>2634 - 14<sup>th</sup> St.</i>			
DATE <i>12/5/42</i>	PURPOSE <i>Make addition to rear of dwlg.</i>			
ZONE	OWNER <i>A. S. McLaughlin, Jr.</i>			
	ARCH'T.			
	CONTR. <i>Owner</i>			
VAL. <i>195<sup>00</sup></i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
12/7/42	1 <sup>st</sup> / HSP. Forms for 1-Rm Addn to rear of Dredg O.K. A.W. Campbell
1/15/43	2 <sup>nd</sup> / HSP. Frame for above <sup>OK</sup> A.W. Campbell
1/29/43	3 <sup>rd</sup> / HSP. INY LATA <sup>OK</sup> A.W. Campbell
3/6/43	4 <sup>th</sup> / HSP. 1-Rm Addn Completed O.K.
7/9/43	COMPLETE AND O. K. <i>Arthur W. Campbell</i> INSPECTOR