

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-11545</i>	LOCATION <i>2331 -- Riverside Blvd.</i>
DATE <i>9/11/43.</i>	PURPOSE <i>Repairs to dwlg. due to fire loss</i>
ZONE	OWNER <i>M. Blackburn</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>5000</i>	STORIES	ROOMS	APTS.	SIZE
------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE.	CONDITION OF WORK-REMARKS
	<p data-bbox="305 949 454 994">COMPLETE AND O. K.</p> <p data-bbox="1268 964 1422 988">INSPECTOR</p>