

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <b>5413</b>	LOCATION <b>740-35</b>		
DATE <b>10/1/59</b>	PURPOSE <b>Repair Roof.</b>	ROOMS	APTS.
ZONE <b>1</b>	OWNER <b>DW Green</b>	PHONE	
	ARCH'T		
	CONT'R <b>Capital Roofing</b>		
	VAL. <b>150-</b>	STORIES <b>1</b>	SIZE <b>0</b>

FOUNDATION	STORY	BSMT	1	2	3	ROOF			
EX WALL	Jolsts						Chimneys		Cement Tests
	Beams and Girders						Fire Place		
Int Wall	Studs and Columns						Gas Water Heater		
	Bridging Fire Stops						Heater Closet		
Piers	Fire Escape Stand Pipes						Furnace		Window Courts
	Metal Lath						Doller Room		
	Stairs						Elevator Shaft		

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="315 844 468 890"><b>COMPLETED AND O.K.</b></p> <p data-bbox="1099 865 1239 890"><b>INSPECTOR</b></p>