

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-11694</i>	LOCATION <i>1323 - E. Street.</i>
DATE <i>10/22/43.</i>	PURPOSE <i>Add two room apart rear</i>
ZONE	OWNER <i>Mary Curson</i>
	ARCH'T.
	CONT'R. <i>Owner</i>

VAL. <i>195⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
10/29/43	1 ST / HSP. Forms for Address to rear ^{OK} A.W. Campbell
2/23/44	2 ND / HSP. Frame for above. ^{OK} A.W. Campbell
	3 RD / HSP. INT. WALLS & CEILING. PLY-BOROI CELETEX ^{OK}
	<p data-bbox="304 888 431 928">COMPLETE AND O. K.</p> <p data-bbox="1164 909 1297 928">INSPECTOR</p>