

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <i>1013</i>	LOCATION <i>2726 = 33" SW</i>		
DATE <i>4/13/33</i>	PURPOSE <i>Repairing Roof</i>	ROOMS	APTS.
ZONE <i>2-Fam</i>	OWNER <i>M. Johnson</i>	PHONE	
	ARCH'T		
	CONT'R <i>Owner</i>		
	VAL. <i>Less than 100</i>	STORIES	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF			
Ex Wall	Jolts						Chimneys		Cement Tests
	Beams and Girders						Fire Place		
Int Wall	Studs and Columns						Gas Water Heater		
	Bridging Fire Stops						Heater Closet		
Piers	Fire Escape Stand Pipes						Furnace		Window Courts
	Metal Lath						Boller Room		
	Stairs						Elevator Shaft		

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="319 840 477 888"><b>COMPLETED AND O.K.</b></p> <p data-bbox="1107 866 1251 888"><b>INSPECTOR</b></p>