

R 223 F1

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$10.00

TYPE BUILDINGS

PERMIT NO. F-8276	LOCATION 551- 46th Street	A-1	
DATE Aug. 21/67	PURPOSE Repair pest damage to dwelling		
OWNER Ruby Dawling	Same		
ZONE	ARCH'T /442-8880		
	CONT'R Midstate Termite Box 8827, Sacto.		
VAL. \$1,000.	STORIES	ROOMS	APTS. SIZE
INSP. DATE	BLDG. TYPE V no hr.	OCCUPANCY GROUP I-1	PHONE (O) (C)
FORM 8-38-67	Trilo (yes)		
JOIST			
FRAME 8-24-67	Fuller	8-30-67	Barbato
SHEET ROCK 8-11-67	Trilo	"certified" 4-7-68	
FINAL 9-11-67	Trilo	D.F. ENT.	

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
9-7-67	No work on south side Cellarway
4-16-68	Sent notice of no final Fall/W
COMPLETE AND OK	INSPECTOR