

R37

1117-189

Lot 8		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD			\$58.00
N. 50 of Lot 7		TYPE BUILDINGS			
E. J. Boden					
PERMIT NO.					
G-177	LOCATION 657 - 38th Street A-1 (15)				
DATE	PURPOSE Const. dwelling with detached garage.				
4/25/68	OWNER Miguel Reta 4217 - Park Road				
ZONE	ARCH'T 383-2505				
	CONTR Florin Ent. 6435 Florin-Perkins Rd.				
VAL.	\$16,500.	STORIES	ROOMS	APTS.	1624 sq.ft. ^{SIZE}
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM	5-8-68	Rolo			
JOIST	5-17-68	Barbato			
FRAME	7-10-68	Barbato			
SHEET ROCK	7-19-68	Rolo			
FINAL	10-17-68	Barbato			



DATE	SPECIAL CONDITIONS OF WORK — REMARKS
5-7-68	P.T. Form #2 Redwood mud sill not allowed, studs
7-17-68	P.T. S.P. not enough, nails studs
8-30-68	P.T. Address: Surveys Clearcase Court
9-12-68	P.T. Stairs on north sides of dwelling shall have risers that are uniform. Bar bats
COMPLETE AND OK	INSPECTOR

