

5159 7353-282

| | | | | |
|----------------|----------|--|---------------------|---------------|
| Lot B | | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD | | \$67.00 |
| Fullertown | | TYPE BUILDINGS | | |
| PERMIT NO. | | | | |
| E-9334 | LOCATION | 5940 - 24th Street | | A-4 |
| DATE | PURPOSE | Const. new service station | | |
| Jan 14-65 | OWNER | H. H. Hendren 1601 - J St. | | |
| ZONE | ARCH'T | | | |
| C-2 | CON'TR | Triangle Const. 3525 - 52nd Ave. | | |
| VAL. \$20,000. | STORIES | ROOMS | APTS. | SIZE |
| INSP. | DATE | BLDG. TYPE IV no hr. | OCCUPANCY GROUP F-1 | PHONE (O) (C) |
| FORM | 1-27-65 | M. Callaway | | |
| JOIST | | | | |
| FRAME | | | | |
| SHEET ROCK | | | | |
| FINAL | 11-10-65 | J. J. Salvo | | |

SPECIAL INSPECTION REQUIRED FOR ALL WORKS REQUIRING PERMITS



| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|--------|--------------------------------------|
| 2-1-65 | COLUMN FOOTINGS OK. (P.L.H.) |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND OK |

INSPECTOR

