

R222 F414

Lot 399		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD			\$55.00
Southgate Meadows #6		TYPE BUILDINGS		R212 F510-517	
PERMIT NO.	LOCATION 7737 Quinby Way A-5				
F-8214					
DATE	PURPOSE Const. dwelling & garage 101 S				
Aug. 14/67	OWNER Center Dev. 2777 Alvarado St., San				
ZONE	ARCH'T /Leandro				
R-1	CONTR Besco 2777 Alvarado St., San Leandro				
VAL	\$15,100.	STORIES	ROOMS	APTS.	462 gar. SIZE 1,525 sq. ft.
		1	5		
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C) 383-9315	
FORM	8-31-67	Lopez			
JOIST	9-18-67	Cost			
FRAME	10-13-67	Lopez			
SHEET ROCK	10-19-67	Lopez			
FINAL	1-19-68	Cost			

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
9-11-67	Pt Membrane - not ready Berlin
9-12-67	OK membrane Lasee
9-15-67	Pt Grit Backfill plumbing Lasee
12-6-67	Pt Locked Lasee
COMPLETE AND OK	INSPECTOR