

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. <i>3911</i>	LOCATION <i>24th Ave 2nd St 2508 N.</i>		
DATE <i>1/31/78</i>	PURPOSE <i>1st floor renovation</i>	ROOMS	APTS.
ZONE	OWNER <i>Condo Union Building</i>		PHONE
	ARCH'T		
	CONT'R <i>W. J. ...</i>		
	VAL. <i>300 -</i>	STORIES	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
Ex Wall	Joists						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand. Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	CONDITION OF WORK—REMARKS
1/9/29	1 st Insp. Brick Piers and 4" Brick Wall + 2 Belasters on East + West Property Lines.
1/9/29	2 nd Insp. Frame for 4 Stall Pans + Lanes in Place. H. Campbell
1/18/29	Final Insp " " Completed. H. Campbell

COMPLETED
AND O. K.

INSPECTOR