

A-73

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD \$3.00

**TYPE BUILDINGS** A-73  
E-458

<b>PERMIT NO.</b> D-6111	<b>LOCATION</b> 1490- 34th Street A-1
<b>DATE</b> Aug. 1, 60	<b>PURPOSE</b> Repair rot damage to dwelling
<b>ZONE</b> R-1	<b>OWNER</b> C. Serano
	<b>ARCH'T</b>
	<b>CONT'R</b> Orchard Supply 1731-17th St. H 1 6-7821

<b>VAL</b> \$475.	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
-------------------	----------------	--------------	--------------	-------------

<b>INSP.</b>	<b>DATE</b>	<b>INSPECTOR</b>
<b>FORM</b>		
<b>JOIST</b>		
<b>FRAME</b>		
<b>LATH</b>		
<b>FINAL</b>	10-26-60	Berney, Dan

THIS REPORT IS VALID FOR THE PERIOD INDICATED ON THE PERMIT

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
COMPLETE AND OK	INSPECTOR