

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-12.</i>	LOCATION <i>1030 - N. Street.</i>
DATE <i>3/4/38</i>	PURPOSE <i>Repairs to stone & dwg.</i>
ZONE	OWNER <i>Mr. E. Greeley J.</i>
	ARCH'T.
	CONTR. <i>Chas Vanina</i>

VAL. <i>258⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK—REMARKS
3/10/38	Repairs to 2-Story Store & Flat Bldg Damaged by storm - Completed O.K. A.W. Campbell
3/11/38	COMPLETE AND O. K. <i>Walter H. Campbell</i> INSPECTOR