

1  
R 197 4546-551

## BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$55.00

## TYPE BUILDINGS

|                      |   |  |                    |                                  |
|----------------------|---|--|--------------------|----------------------------------|
| PERMIT NO.<br>F-4690 | LOCATION<br>1348 - 37th Street                | A-1  |                    |                                  |
| DATE<br>July 1-66    | PURPOSE<br>Const. dwlg. & att. carport & att. | OWNER<br>Esther Fitzgerald / patio & storeroom |                    |                                  |
| ZONE<br>R-1          | ARCH'T<br>Rt. 8, Freeport                     | CON'TR<br>Donald Nevis 1205-Nevis Court        |                    |                                  |
| VAL. \$15,600.       | STORIES                                       | ROOMS  | APTS.              | 270-carport SIZE<br>1350 sq. ft. |
| INSP.                | DATE  | BLDG.<br>TYPE                                  | OCCUPANCY<br>GROUP | PHONE (O) (C)                    |
| FORM                 | 7-13-66                                       | Larson   |                    |                                  |
| JOIST                | 7-20-66                                       | Larson   |                    |                                  |
| FRAME                | 8-17-66                                       | Larson   |                    |                                  |
| SHEET<br>ROCK        | 8-23-66                                       | Fuller   |                    |                                  |
| FINAL                | 10/12/66                                      | Dana Fuller                                    |                    |                                  |

E



1

| DATE               | SPECIAL CONDITIONS OF WORK — REMARKS                                 |
|--------------------|--|
| 9-16-66            | PK frame - 2 x 8 ceiling joists must<br>be solid blasted at each end |
|                    |  |
|                    |  |
|                    |  |
|                    |  |
|                    |  |
|                    |  |
|                    |  |
| COMPLETE<br>AND OK | INSPECTOR  |

