

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-5812</i>	LOCATION <i>430 - 1 St.</i>
DATE <i>3/5/37</i>	PURPOSE <i>Remod of interior</i>
ZONE	OWNER <i>Capital Co. Travelers Hotel</i>
	ARCH'T.
	CONTR <i>Capital Co</i>

VAL. <i>15000<sup>00</sup></i>	STORIES	ROOMS	APTS.	SIZE
--------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
3/11/37	2 <sup>nd</sup> WSP Frame for Attention & Stress and Tile Ceiling in room on 11 <sup>th</sup> floor O.K. A.W. Campbell
3/24/37	3 <sup>rd</sup> WSP. Int. Me. ceiling and plaster in addition done - to be on 11 <sup>th</sup> floor. A.W. Campbell
4/27/37.	Safety of work informed me all the glass sides in light ponds to be removed and replaced with Red Cone panels method. A.W. Campbell
	COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span>