

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>8588.</i>	LOCATION <i>2018 9 St.</i>
DATE <i>9/14/31</i>	PURPOSE <i>Repair</i>
ZONE <i>Multifam</i>	OWNER <i>Thomas Donnellie Atkins</i>
	ARCH'T
	CONT-R <i>J. G. Lawrence</i>
	PHONES

VAL. <i>135</i>	STORIES	ROOMS	APTS.	SIZE
--------------------	---------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
	<p data-bbox="354 965 534 1020">COMPLETE AND O.K.</p> <p data-bbox="1273 994 1458 1020">INSPECTOR</p>